STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	30984	A. BUILDING: _____ B. WING _____	11/13/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ANNIE'S HOUSE INC	25228 BUZZARD DRIVE MARBLE HILL, MO 63764

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A2268	19 CSR 30-86.022(11)(A) Complete Sprinkler System-NFPA 13 Sprinkler Systems. (A) Facilities licensed on or after August 28, 2007, or any section of a facility in which a major renovation has been completed on or after August 28, 2007, shall install and maintain a complete sprinkler system in accordance with NFPA 13, 1999 edition. I/II This regulation is not met as evidenced by: Class II Based on observation and interview the facility failed to maintain the sprinkler system in accordance with the applicable edition of National Fire Protection Association (NFPA) 13. The facility has sprinkler heads and escutcheon rings on the sprinkler piping that has fallen down below the normal sprinkler mounting position leaving a space between the escutcheon ring and the finished ceiling. If there is a space between the escutcheon ring and the ceiling or wall, fire and smoke could travel into adjoining spaces and make the sprinkler system ineffective. The facility census was thirty nine (39). This deficiency affects thirty nine (39) of thirty nine (39) residents. Observation on November 13, 2025 at 10:18 A.M. showed three (3) sprinkler heads in the game room area that have fallen and hanging below the normal mounted position on the finished ceiling. The sprinkler head being below the normal position leaves an open space between the finished ceiling the escutcheon ring by approx. one half inch (1/2"). Observation on November 13, 2025 at 10:45 A.M. showed a sprinkler head in the men's restroom fifty one (51) that has fallen and hanging below	A2268		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	30984	A. BUILDING: _____ B. WING _____	11/13/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ANNIE'S HOUSE INC	25228 BUZZARD DRIVE MARBLE HILL, MO 63764

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A2268	Continued From page 1 the normal mounted position on the finished ceiling. The sprinkler head being below the normal position leaves an open space between the finished ceiling the escutcheon ring by approx. one half inch (1/2"). During an interview on November 13, 2025 at 11:30 A.M. the administrators assistant said she was not aware the rings were not in the correct position and that she would contact the sprinkler company to have the issues corrected.	A2268		
A2278	19 CSR 30-86.022(12)(C) Emergency Lighting -Battery Powered, 1.5 hrs Emergency Lighting. (C) If battery-powered lights are used, they shall be capable of operating the light for at least one and one-half (1 1/2) hours. II This regulation is not met as evidenced by: Class II Based on observation and interview the facility failed to maintain the building's emergency lighting in good repair. The facility census was thirty nine (39). This deficiency affects thirty nine (39) of thirty nine (39) residents. Observation on November 13, 2025 at 10:55 A.M. showed the emergency exit light located at the hallway exit beside resident room thirty five (35) failed to function when the test button was depressed. During an interview on November 13, 2025 at 11:30 A.M. the administrators assistant stated she was not aware the emergency light was not working, and will let the administrator know.	A2278		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	30984	A. BUILDING: _____ B. WING _____	11/13/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ANNIE'S HOUSE INC	25228 BUZZARD DRIVE MARBLE HILL, MO 63764

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A3214	19 CSR 30-86.032(13) Electrical Wiring, Maintained, Inspected In facilities that are constructed or have plans approved after July 1, 2005, electrical wiring shall be installed and maintained in accordance with the requirements of the National Electrical Code, 1999 edition, National Fire Protection Association, Inc., incorporated by reference, in this rule and available by mail at One Batterymarch Park, Quincy, MA 02269, and local codes. This rule does not incorporate any subsequent amendments or additions to the materials incorporated by reference. Facilities built between September 28, 1979 and July 1, 2005 shall be maintained in accordance with the requirements of the National Electrical Code, which was in effect at the time of the original plan approval and local codes. This rule does not incorporate any subsequent amendments or additions. In facilities built prior to September 28, 1979, electrical wiring shall be maintained in good repair and shall not present a safety hazard. All facilities shall have wiring inspected every two (2) years by a qualified electrician. II/III This regulation is not met as evidenced by: Class III Based on observation,record review and interview the facility failed to properly maintain the electrical wiring system to not cause a safety and/or fire hazard. The facilit also failed to have wiring inspected every two (2) years by a qualified electrician. The facility census was thirty nine (39). This deficiency affects thirty nine (39) of thirty nine (39) residents. Record review on November 13, 2025 at 10:00 A.M. showed no current semi annual electrical inspection on file for review. The last documented	A3214		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	30984	A. BUILDING: _____ B. WING _____	11/13/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ANNIE'S HOUSE INC	25228 BUZZARD DRIVE MARBLE HILL, MO 63764

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A3214	Continued From page 3 inspection on file was dated September 2023. Observation on November 13, 2025 at 10:01 A.M. showed two (2) unapproved electrical extension cords in use in resident room one (1). The extension cords were being used to power lights and a television. Observation on November 13, 2025 at 10:20 A.M. showed an unapproved electrical extension cord in use in resident room eleven (11). The extension cords were being used to power lights and a phone charger. Observation on November 13, 2025 at 10:27 A.M. showed an unapproved electrical extension cord in use in resident room seventeen (17). The extension cords was hanging form the curtain rod and was being used to power Christmas lights. Observation on November 13, 2025 at 10:31 A.M. showed an unapproved electrical extension cord rolled up in the floor of resident room twenty one (21). Observation on November 13, 2025 at 10:35 A.M. showed an open electrical wiring connection under the top bunk bed in resident room twenty one (21). The end of an electrical extension cord had been removed and wired together with a clip on style bed reading light. The electrical connection was made using electrical tape to hold it together. The light was immediately removed from use by maintenance due to the extreme hazard it presented to the resident and property. Observation on November 13, 2025 at 10:40 A.M. showed an electrical outlet on the south wall of resident room twenty one (21) was missing the protective cover plate.	A3214		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	30984	A. BUILDING: _____ B. WING _____	11/13/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ANNIE'S HOUSE INC	25228 BUZZARD DRIVE MARBLE HILL, MO 63764

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A3214	Continued From page 4 Observation on November 13, 2025 at 10:48 A.M. showed two (2) unapproved electrical multiplug adapters in use in resident room twenty seven (27). The adapters were used to power lights and a fan. Observation on November 13, 2025 at 10:58 A.M. showed an unapproved electrical multiplug adapter in use in resident room thirty five (35). The adapter was used to power a phone charger. During an interview on November 13, 2025 at 11:30 A.M. the administrative assistant stated she was not aware of the electrical issues or a cords being in use. She stated she will let the owner know and have the issues taken care of. She stated she had spoken to the owner about the electrical inspection and was told the electrician who was supposed to take care of the inspection had not returned to perform the inspection, he had been to the other facility but had not returned to perform the inspection at this location, he was contacted and will be coming to perform the inspection.	A3214		

PLAN OF CORRECTION

Provider/Supplier Name:	Annie's House, Inc.
Street Address, City, Zip:	25228 Buzzard Dr. Marble Hill, MO 63764
Date of Survey:	November 13, 2025
PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER	30984

ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION: (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	COMPLETION DATE
A2268	Sprinkler System – see attached correction	11/18/2025
A2278	Emergency Lighting – see attached correction	11/18/2025
A3214	Electrical Wiring Inspection – see attached correction	11/24/2025
	Electrical Wiring Extension Cords	11/18/2025
	Electrical Wiring Open	11/13/2025
	Electrical Wiring Protective Cover	11/14/2025
	Electrical Wiring Multiplugs	11/18/2025

The Administrator signing and dating the first page of the CMS-2567/State Form is indicating their approval of the plan of correction being submitted on this form.

Missouri Department of Health and Senior Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	30984	A. BUILDING: _____ B. WING _____	11/13/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ANNIE'S HOUSE INC	25228 BUZZARD DRIVE MARBLE HILL, MO 63764

11/28/25 Andrea D. Cook

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A2268	19 CSR 30-86.022(11)(A) Complete Sprinkler System-NFPA 13 Sprinkler Systems. (A) Facilities licensed on or after August 28, 2007, or any section of a facility in which a major renovation has been completed on or after August 28, 2007, shall install and maintain a complete sprinkler system in accordance with NFPA 13, 1999 edition. I/II This regulation is not met as evidenced by: Class II Based on observation and interview the facility failed to maintain the sprinkler system in accordance with the applicable edition of National Fire Protection Association (NFPA) 13. The facility has sprinkler heads and escutcheon rings on the sprinkler piping that has fallen down below the normal sprinkler mounting position leaving a space between the escutcheon ring and the finished ceiling. If there is a space between the escutcheon ring and the ceiling or wall, fire and smoke could travel into adjoining spaces and make the sprinkler system ineffective. The facility census was thirty nine (39). This deficiency affects thirty nine (39) of thirty nine (39) residents. Observation on November 13, 2025 at 10:18 A.M. showed three (3) sprinkler heads in the game room area that have fallen and hanging below the normal mounted position on the finished ceiling. The sprinkler head being below the normal position leaves an open space between the finished ceiling the escutcheon ring by approx. one half inch (1/2"). Observation on November 13, 2025 at 10:45 A.M. showed a sprinkler head in the men's restroom fifty one (51) that has fallen and hanging below	A2268	On November 18th, 2025 Annie's House corrected the sprinkler head to the correct position and did a walk through of the facility checking all other sprinkler heads for the appropriate spacing. Annie's will continue monitoring the spacing of each sprinkler head during monthly routine checks of the system to ensure the appropriate spacing is being met. All sprinkler heads will be observed and documented to have met the appropriate spacing to ensure this does not go unmet in the future.	11/18/2025