

THE FACILITY DID NOT RETURN A
PLAN OF CORRECTION
THEREFORE, NO POC IS INCLUDED
WITH THE STATEMENT OF
DEFICIENCIES (2567 FORM)

Missouri Department of Health and Senior Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 28242	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 05/27/2025
--	--	---	---

NAME OF PROVIDER OR SUPPLIER SUNRISE OF WEBSTER GROVES	STREET ADDRESS, CITY, STATE, ZIP CODE 45 EAST LOCKWOOD SAINT LOUIS, MO 63119
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A3214	<p>19 CSR 30-86.032(13) Electrical Wiring, Maintained, Inspected</p> <p>In facilities that are constructed or have plans approved after July 1, 2005, electrical wiring shall be installed and maintained in accordance with the requirements of the National Electrical Code, 1999 edition, National Fire Protection Association, Inc., incorporated by reference, in this rule and available by mail at One Batterymarch Park, Quincy, MA 02269, and local codes. This rule does not incorporate any subsequent amendments or additions to the materials incorporated by reference. Facilities built between September 28, 1979 and July 1, 2005 shall be maintained in accordance with the requirements of the National Electrical Code, which was in effect at the time of the original plan approval and local codes. This rule does not incorporate any subsequent amendments or additions. In facilities built prior to September 28, 1979, electrical wiring shall be maintained in good repair and shall not present a safety hazard. All facilities shall have wiring inspected every two (2) years by a qualified electrician. II/III</p> <p>This regulation is not met as evidenced by: Class III</p> <p>Based on document review and interview on May 27, 225, the facility failed to insure the facility's electric wiring was inspected every two (2) years by a qualified electrician. The facility census was 83. This deficiency affects 83 out of 83 residents.</p> <p>Document review at 11:45 A.M. showed the facility failed to have the electric wiring inspected every 2 years. Further review showed the last electrical inspection was done on Feburary 3, 2023.</p>	A3214		

Missouri Department of Health and Senior Services LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
--	-------	-----------

Missouri Department of Health and Senior Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 28242	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 05/27/2025
--	--	---	---

NAME OF PROVIDER OR SUPPLIER SUNRISE OF WEBSTER GROVES	STREET ADDRESS, CITY, STATE, ZIP CODE 45 EAST LOCKWOOD SAINT LOUIS, MO 63119
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A3214	Continued From page 1 During an interview on May 27, 225 at the time of discovery, the Facilities Manager stated he/she would have the inspection done.	A3214		