



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	New Westside Terrace	Provider Number	001590
Address	1200 17TH AVE ,	Approval Status	Approved
City, State, Zip	Longview, WA 98632	Facility Type	Residential Care

On 06/12/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Marisa Jimenez
Signature

Marisa Jimenez Galvan
Print Name and Title

Deputy State Fire Marshal Nicholas Wolden
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966

Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Business Name	New Westside Terrace	Provider Number	001590
Address	1200 17TH AVE ,	Approval Status	Disapproved
City, State, Zip	Longview, WA 98632	Facility Type	Residential Care

On 05/01/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Duct and Air Transfer Openings - Maintaining Protection

<p>Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced.</p> <p>(IFC 706.1 2018)</p>	<p>Facility failed to provide the following reports</p> <p>4 year fire damper inspection</p>
--	--

2 Testing and Maintenance

<p>Sprinkler systems shall be tested and maintained in accordance with Section 901.</p> <p>(IFC 903.5 2009, 2012, 2015, 2018)</p>	<p>Facility failed to provide the following reports</p> <p>Annual fire sprinkler inspection Annual forward flow of sprinkler system Quarterly fire sprinkler inspection</p>
---	---

3 Smoke Detector Sensitivity

<p>Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.</p> <p>(IFC 907.8.3 2012, 2015, 2018)</p>	<p>Facility failed to provide the following reports</p> <p>Sensitivity testing for fire alarm system</p>
---	--

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	New Westside Terrace	Provider Number	001590
Address	1200 17TH AVE ,	Approval Status	Disapproved
City, State, Zip	Longview, WA 98632	Facility Type	Residential Care

On 05/01/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 05/31/2023

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Maria Jimenez
Signature

Mariisa Jimenez
Print Name and Title

Deputy State Fire Marshal Nicholas Wolden
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966

Signature

Initials of Authorized Facility Representative: MRJ

This document was prepared by Residential Care Services for the Locator website.