

## NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Meridian Meadows Assisted Living	RC-1228	2584 East Magic View Drive	208-506-5130
Administrator	City	Zip Code	Survey Date
Tomi Mooney	Meridian	83642	02/18/2025
Survey Team Leader	Survey Type		Response Due
Wilson, Jeremy	fire life safety and sanitation licensure		03/20/2025

Item #	Rule (16.03.22)	Description
1	.405.01. Electrical Installations and Equipment.	During facility tour it was identified in the back of house electrical room, the electrical panels were blocked from access by furniture and landscaping tools. Clearance to electrical panels shall be in compliance with NFPA 70, Article 100, Section 110.26(a)
2	.405.01.a. Electrical Installations and Equipment.	During facility tour it was identified in room #302 a lamp, clock and charger being supplied power by a multi-plug adapter. Multi-plug adapters are prohibited.
3	.405.04. Fuel-Fired Heating.	Based on provided maintenance records, the last documented fuel-fired heating systems inspection was conducted in November 2022. Fuel-fired heating systems shall be inspected annually.
4	.404. FIRE AND LIFE SAFETY STANDARDS FOR EXISTING BUILDINGS LICENSED FOR SEVENTEEN OR MORE RESIDENTS AND MULTI-STORY BUILDINGS.	1) Back of house medical records storage room is larger than 50 square feet and contains a high level of combustible material deeming the room a hazardous area in accordance with NFPA 101, Chapter 33, Section 33.3.3.2.2 and shall have a self-closing door. 2) Sprinkler pendant located in medical records storage room is covered in non-factory applied paint/ overspray and shall be replaced in accordance with NFPA 25, Chapter 5, Section

		<p>5.2.1.1.1.</p> <p>3) Sprinkler pendants located in kitchen above main cook line and 3 compartment sink are corroded and shall be replaced in accordance with NFPA 25, Chapter 5, Section 5.2.1.1.1.</p> <p>4) Sprinkler pendant located in dish-washing area is loaded with debris and shall be replaced in accordance with NFPA 25, Chapter 5, Section 5.2.1.1.1.</p> <p>5) Emergency egress and exit lighting shall be operationally tested 30 seconds monthly and for 90 minutes on an annual basis in accordance with NFPA 101, Chapter 7, Section 7.9.3.</p> <p>6) Storage closet located next to room #203 has a 1 1/2" annular penetration into the interstitial ceiling cavity created by the lighting escutcheon eliminating the continuity of the smoke partition membrane and shall comply with NFPA 101, Chapter 8, Section 8.4.2.</p>
5	.330.15. Fire and Life Safety Records.	<p>1) Documentation could not be provided for annual inspection of portable fire extinguishers.</p> <p>2) Documentation could not be provided for 1 of the 2 required semi-annual fire suppression system inspections and testing of the UL listed hood assembly in the commercial grade kitchen.</p>
6	.405.02.a. Prohibited Applications.	During facility tour it was identified in room # 307, an oxygen concentrator being supplied power though a relocatable power tap (RPT). The use of a RPT to supply power to a medical device is prohibited.