

CORE ISSUES

Facility	License #	Physical Address	Phone Number
Edgewood Billings Senior Living, LLC	12786	1225 Wicks Ln	406-256-5398
Administrator	City	Zip Code	Survey Date
	Billings	59105	02/23/2018
Survey Team Leader	Survey Type		Response Due
Pluhar, Brinda	Renewal Inspection		03/05/2018

Item #	Rule ()	Description
1	37.106.2829-2 RESIDENT FILE	Review of resident #1 file; no documentation of the date and circumstances of the resident's final transfer, discharge, or death, including notice to responsible parties and disposition of personal possessions.
2	37.106.2838-7 RESIDENT TOILETS AND BATHING	Tour of facility; of the 18 rooms/bathrooms inspected, one had no emergency call system in the bathroom and 11 had call systems in the bathrooms but the pull cords were not accessible to an individual collapsed on the floor.
3	37.106.2861-2 LAUNDRY	Tour of facility; laundry room didn't have adequate ventilation in the sorting, holding and processing area to prevent heat and odor build-up. The room was very warm and smelled of urine. One small vent was being used but it was not adequate.
4	37.106.2865-8 PHYSICAL PLANT	Facility tour; grab bars in the tub rooms in Wing A and B were loose and not sufficiently anchored to sustain a concentrated 250-pound load.