

Community Care Licensing

FACILITY EVALUATION REPORT

Facility Number: 198320197

Report Date: 04/19/2021

Date Signed: 04/28/2021 02:29:27 PM

Document Has Been Signed on 04/28/2021 02:29 PM - It Cannot Be Edited

STATE OF CALIFORNIA - HEALTH AND HUMAN SERVICES AGENCY	CALIFORNIA DEPARTMENT OF SOCIAL SERVICES COMMUNITY CARE LICENSING DIVISION CCLD Regional Office, 1000 CORPORATE DR #100 MONTEREY PARK, CA 91754
FACILITY EVALUATION REPORT	

FACILITY NAME:	PLAZA AT WESTWOOD, THE	FACILITY NUMBER:	198320197
ADMINISTRATOR:	ZENTENO, VIRGINIA	FACILITY TYPE:	740
ADDRESS:	2228 WESTWOOD BLVD	TELEPHONE:	(323) 217-7877
CITY:	LOS ANGELES	ZIP CODE:	90064
CAPACITY:	136	CENSUS:	41
TYPE OF VISIT:	Prelicensing	ANNOUNCED	DATE: 04/19/2021
MET WITH:	Sholomo "Steven" Aron	TIME BEGAN:	09:00 AM
		TIME	11:00 AM
		COMPLETED:	

NARRATIVE	
1	Licensing Program Analyst (LPA) Troy Agard conducted an announced visit to the above facility for
2	purpose of a pre-licensing evaluation. Due to the situation surrounding the Coronavirus Disease 2019
3	(COVID-19), and to implement mitigation measures, today's inspection was conducted via FaceTime
4	with Licensee Representative, Sholomo "Steven" Aron. During the inspection LPA toured the inside and
5	outside of the facility and verified the address of the location.
6	
7	An application was submitted to CCLD on 03/02/2021 for a change of ownership for a Residential Care
8	Facility for the Elderly to serve seniors and seniors with dementia, ages 60 years and greater. The
9	requested capacity is for 136. 130 non-ambulatory and 6 bedridden. Facility has a fire clearance dated
10	for 04/07/2021.
11	
12	<u>Structure:</u> Facility is a 68 resident-bedroom, approx.74-bathroom, three-story building. 1st floor consists
13	of a lobby area, laundry facility, staff break room and an adjacent parking structure. 2 nd floor consists of
14	residential rooms, dining room, kitchen, outdoor patio, media room and medication room. The 3 rd floor
15	consists of resident rooms and storage. The Resident bedrooms are spacious and easily accommodate
16	furnishings. There is a shaded patio / courtyard area with tables and chairs. Shaded area has sufficient
17	tables and chairs for residents. Outdoor passageways, walkways, driveways, steps and patios are free
18	from obstructions. LPA did not observe hazards, such as ladders, gardening tools and/or motorized
19	equipment in the front, back and/or side areas of the facility.
20	
21	<u>Bedrooms:</u> All bedrooms have a chair, nightstands, over-head lighting, dressers and closets. The closets
22	and drawers comply with the requirement of 8 cubic feet of space.
23	
24	
25	
	<u>Office:</u> Facility has few offices with desk, chairs and cabinets with staff records, and resident records.

NAME OF LICENSING PROGRAM MANAGER: Angela J Kendrick

NAME OF LICENSING PROGRAM ANALYST: Troy Agard

LICENSING PROGRAM ANALYST SIGNATURE:**DATE:** 04/27/2021

I acknowledge receipt of this form and understand my licensing appeal rights as explained and received.

FACILITY REPRESENTATIVE SIGNATURE:**DATE:** 04/27/2021

This report must be available at Child Care and Group Home facilities for public review for 3 years.

LIC809 (FAS) - (06/04)

Page: 1 of 3

STATE OF CALIFORNIA - HEALTH AND HUMAN SERVICES AGENCY

CALIFORNIA DEPARTMENT OF SOCIAL

FACILITY EVALUATION REPORT (Cont)

SERVICES

COMMUNITY CARE LICENSING DIVISION

CCLD Regional Office, 1000 CORPORATE DR #100
MONTEREY PARK, CA 91754**FACILITY NAME:** PLAZA AT WESTWOOD, THE**FACILITY NUMBER:** 198320197**VISIT DATE:** 04/19/2021**NARRATIVE**

1 Reading Material, Games, Equipment & Materials: The facility has board games, books, and other
2 recreational materials for the client's use as well as an activity calendar.
3
4 Pool/Jacuzzi & Pets: LPA's did not observe any pet or bodies of water at the facility.
5
6 Fire clearance: Fire Clearance was approved on 04/07/2021 for 130 non-ambulatory and 6 bedridden
7 residents. LPA did not observe pad locks or other mechanisms which may be obstructions for safe and
8 quick egress during an emergency on front and back exits.
9
10 Component III: Conducted at the Pre-Licensing visit, on 04/19/2021 at PLAZA AT WESTWOOD, THE.
11 Information was provided about how to operate the facility within substantial compliance.
12
13 During the pre-licensing inspection no items were observed which do not comply with applicable laws
14 and regulations; no items require a follow up inspection for verification of correction.
15
16 Pre-Licensing is complete, and this facility has no deficiencies.
17
18 An exit interview was conducted, and a copy of this report has been furnished to the applicant via email
19 for signature.
20
21 Accordingly, LPA will submit a copy of this facility evaluation report to the Central Applications Bureau
22 (CAB) for review. If the applicant has questions regarding the status of the application, they have been
23 instructed to communicate with the CAB Analyst assigned to the applicant.
24
25
26
27
28
29
30
31
32

NAME OF LICENSING PROGRAM MANAGER: Angela J Kendrick**NAME OF LICENSING PROGRAM ANALYST:** Troy Agard**LICENSING PROGRAM ANALYST SIGNATURE:****DATE:** 04/27/2021

I acknowledge receipt of this form and understand my licensing appeal rights as explained and received.

FACILITY REPRESENTATIVE SIGNATURE:**DATE:** 04/27/2021

LIC809 (FAS) - (06/04)

Page: 3 of 3

STATE OF CALIFORNIA - HEALTH AND HUMAN SERVICES AGENCY

CALIFORNIA DEPARTMENT OF SOCIAL

SERVICES

COMMUNITY CARE LICENSING DIVISION

FACILITY EVALUATION REPORT (Cont)

CCLD Regional Office, 1000 CORPORATE DR #100
MONTEREY PARK, CA 91754

FACILITY NAME: PLAZA AT WESTWOOD, THE

FACILITY NUMBER: 198320197

VISIT DATE: 04/19/2021

NARRATIVE

1 Bathrooms: Facility has approx. 74 bathrooms (68 full baths and 6 half). Bathrooms where observed to
2 have a working toilet, wash basin and shower.
3
4 Linens & Hygiene Supplies: Beds have the required linen/supplies which include, pillowcase, mattress
5 pads, fitted sheet, blanket and bedspreads. Adequate supply of linen; sheets, pillowcases, bath towels
6 are provided. Facility does not provide hygiene supplies to residents.
7
8 Emergency Phone Numbers, Exit Plan & Menu: The telephone, which is a land line, was called by LPA
9 and is operational. Emergency Disaster Plan and "See something, Say something, Let Us Know" posted
10 & readily available for review on the wall throughout the facility. Fully charged fire extinguishers was
11 found throughout the facility.
12
13 Food Service: Dishes, cups and flatware are stored in the kitchen cupboards, inspected and in good
14 repair. Knives, cutlery and other sharp kitchen utensils are stored in a locked drawer in kitchen. Food
15 supply was adequately stored in kitchen refrigerator, cabinets and pantry and consists of the following: a
16 variety of fresh and canned fruit, vegetables and meats all dated.
17
18 Smoke Detectors: dual smoke and carbon monoxide detectors are hardwired and interconnected. All
19 were operational linked to the fire department.
20
21 Appliances: Stove burners, oven, microwave, washer, and dryer are in working order. There is 1 large
22 walk-in refrigerator in the kitchen and 1 large walk-in freezer. Refrigerator and freezer are at the correct
23 temperature for food storage.
24
25
26
27
28 Toxins: Locked/stored and inaccessible to residents.
29
30 Medications, First-Aid Kit & Book: Area for medication storage is in medication room. First aid kit was
31 inspected which has at least the following: thermometer, tweezers, scissors, antiseptic, bandages,
32 gauze. First aid and medications are available for staff use but inaccessible to clients.

Clients & Staff Files: Records of staff and clients are stored and locked in the office of the Administrator.

NAME OF LICENSING PROGRAM MANAGER: Angela J Kendrick

NAME OF LICENSING PROGRAM ANALYST: Troy Agard

LICENSING PROGRAM ANALYST SIGNATURE:

DATE: 04/27/2021

I acknowledge receipt of this form and understand my licensing appeal rights as explained and received.

FACILITY REPRESENTATIVE SIGNATURE:

DATE: 04/27/2021